



* CZ and RZ form a Zobel network. Install only if required for the input transformer.

** JMP1: Connect TX1 pin 2 to 3 for series primaries.
Connect TX1 pin 1 to 2 and pin 3 to 4 for parallel primaries.